


Read Contaminated Codes

This flyer demonstrates DolphiScan's LOCUS Ultrasound Reader on a contaminated Data Matrix. The image shown below (to the right) is generated using the LOCUS Ultrasound Reader with the SoundVision decode software.

The DMx is marked on a steel plate and has been contaminated by rust.



Contaminated DMx on a steel plate

DMx Parameters:

- DMx size: 16x16
- Cell size: 0.5 mm / 0.020 inches
- Marking method: Dot Peen
- DMx Issue: Contaminated by rust